TOWN OF PHILLIPSBURG

Most Common Certificate of Habitability Violations

- 1. Smoke Detectors and Carbon Monoxide Detectors:
 - ~Dining or living room ceiling
 - ~Basement near the bottom of the stairs (two in a large basement)
 - ~Second and third floor hallways (outside bedrooms)
 - ~All CO detectors must be within 10 feet of all sleeping areas
 - ~ Fire Extinguisher must be minimum 2A 10 BC but no larger than 10 lb. & must be mounted in or within

10 ft. of kitchen. Top of extinguisher must not be more than 5 ft. from floor.

Must not mount extinguisher in area blocked by stove!**

- 2. Electrical:
 - ~Minimum of two receptacles per habitable room (7' x 10'). A larger room requires more.
 - ~G.F.I. receptacle in the bathroom and exterior and all kitchen counter tops
 - ~Grounded receptacle for laundry outlet
 - ~Stairway lighting and switch
 - ~Switch for existing pull-chain ceiling lights in habitable rooms
 - ~100-amp service (if existing service requires replacement)
 - ~Faulty wiring, bad splices, open junction boxes
 - ~No visible knob & tube wiring in unit
- 3. Windows:
 - ~All windows must be operable
 - ~Hardware or sash cord should hold windows open, not sticks
- 4. Plumbing & Heating:
 - ~Leaks
 - ~Connection to town sewer
 - ~Documentation of furnace service
- 5. Handrails and Guardrails:
 - ~Stairs more than three risers require handrails
 - ~Porches over 30" high require guardrails with balusters

6. Exterior and Interior Structural:

- ~Painting (exposed wood, peeling and flaking paint)
- ~Siding repairs
- ~Sidewalks cracked, crumbling or buckled
- ~Missing or loose slate or shingles
- ~Chimneys in need of repair or re-grouting
- ~Large holes in walls
- ~Loose and broken stairs
- ~Gutters and downspouts in good repair
- 7. Debris Removal:
 - ~Attics, basements and yards

IT IS ULTIMATELY YOUR RESPONSIBILITY TO ASCERTAIN THE NEED FOR ANY PERMITS TO CORRECT ANY OF THE VIOLATION!

**All repairs or construction shall be done in accordance with all applicable codes. These are only the most common problems found during C/H inspections; other violations, as per the adopted "Existing Structure Code," may be found.

***If violations are found, it will be your responsibility to correct them and contact the office to arrange an appointment for a re-inspection.

For clarification, please call (908) 454-5500, Ted @ extension 312 or Paul extension 313.